



1315

D-HSS



Mat.: HSS




1315 - d₁ x L₁

a	k	d ₂	r ^{-0.02}	d ₁	L ₁ =71	L ₁ =80	L ₁ =100	L ₁ =110
1	3	3	3,5	2	■	■	■	
		4,5	6,5	3	■	■	■	
		5,5	8	4	■	■	■	
1,5	4	7	10	5	■	■	■	
		9	10	6	■	■	■	
		11	12	8	■	■	■	■
		14	15	10	■	■	■	■
		17	15	13	■	■	■	■
		20	15	16	■	■	■	■
		25	15	20	■	■	■	■

1316

C-HSS



Mat.: HSS



1316 - d₁ x L₁/d₃ x L₂

a	k	r ^{-0.02}	d ₂	d ₁	L ₁ =71	L ₁ =80	L ₁ =100	L ₁ =110	d ₃	L ₂			d ₃
1	3	3,5	3	2	■	■	■		0,50-1,99	8	10		0,01
		6,5	4,5	3	■	■	■		0,80-2,99	8	10		
		8	5,5	4	■	■	■		1,00-3,99	8	10		
1,5	4	10	7	5	■	■	■		1,50-4,99	8	10	13	
		10	9	6	■	■	■		1,60-5,99	8	10	13	
		12	11	8	■	■	■	■	2,50-7,99	10	13	19	
		15	14	10	■	■	■	■	4,00-9,99	10	13	19	
		15	17	13	■	■	■	■	5,00-12,99	10	13	19	
		15	20	16	■	■	■	■	8,00-15,99	13	19	25	
		15	25	20	■	■	■	■	12,00-19,99	13	19	25	